

# KIT 372

**SC / YSUS REPAIR KIT**

PANASONIC

TNPA5330

TXP42ST30, TXP42VT30, TXP42GT30

**FAULT SYMPTOM**

**S/C'S TO SC (YSUS) BOARD**

**©2015-2019 Ohm Supplies Ltd**

**Produced for ASWO International Service GmbH**

**DO NOT REPRODUCE**



<u>CCT REF</u>	<u>DESCRIPTION</u>
Q621	P363K2
Q622	P363K2
Q623	P363K2
Q401	P363K2
Q402	P363K2
Q403	P363K2
Q421	P363K2
Q422	P363K2
Q423	P363K2
Q441	P363K2
Q451	P363K2
D421	RF1501
D401	RF1501
D643	RF1501
D642	RF1501
IC502	D68903
Q531	3YDK4
R507	22R
R531	10R