



EDPL 162-B



before



cleaned

S D G

3055L

D

— damaged resistor Source 3055L

— burnt track